FILLTITE WOOD HARDENER RESIN

Page: 1

Compilation date: 18/06/2014

Revision date: 29/10/20

Revision No: 3

Section 1: Identification of the substance/mixture and of the company/undertaking

1.1. Product identifier

Product name: FILLTITE WOOD HARDENER RESIN

Product code: R119

1.2. Relevant identified uses of the substance or mixture and uses advised against

Use of substance / mixture: Wood repair solution

1.3. Details of the supplier of the safety data sheet

Company name: Tembe DIY & Building Products Limited

Delta Court

Sky Business Park Robin Hood Airport

Doncaster DN9 3GN

Tel: +44 (0) 1302 770 234

Email: sales@tembediy.com

1.4. Emergency telephone number

Emergency tel: +44 (0) 1302 770234

(office hours only)

Section 2: Hazards identification

2.1. Classification of the substance or mixture

Classification under CLP: Flam. Liq. 2: H225; Eye Irrit. 2: H319; STOT SE 3: H336; -: EUH066

Most important adverse effects: Repeated exposure may cause skin dryness or cracking. Highly flammable liquid and

vapour. Causes serious eye irritation. May cause drowsiness or dizziness.

2.2. Label elements

Label elements:

Hazard statements: EUH066: Repeated exposure may cause skin dryness or cracking.

H225: Highly flammable liquid and vapour.

H319: Causes serious eye irritation.

H336: May cause drowsiness or dizziness.

Hazard pictograms: GHS02: Flame

GHS07: Exclamation mark





FILLTITE WOOD HARDENER RESIN

Page: 2

Signal words: Danger

Precautionary statements: P102: Keep out of reach of children.

P210: Keep away from heat, hot surfaces, sparks, open flames and other ignition

sources. No smoking.

P233: Keep container tightly closed.

P242: Use non-sparking tools.

P243: Take action to prevent static discharges.

P261: Avoid breathing vapours/spray.

P264: Wash hands, forearms and face thoroughly after handling.

P271: Use only outdoors or in a well-ventilated area.

P280: Wear protective gloves/protective clothing/eye protection/face protection.

P303+P361+P353: IF ON SKIN (or hair): Take off immediately all contaminated clothing.

Rinse skin with water /shower.

P304+P340: IF INHALED: Remove person to fresh air and keep comfortable for

breathing.

P305+P351+P338: IF IN EYES: Rinse cautiously with water for several minutes. Remove

contact lenses, if present and easy to do. Continue rinsing.

P337+P313: If eye irritation persists: Get medical advice/attention.

P370+P378: In case of fire: Use foam to extinguish.

P403+P235: Store in a well-ventilated place. Keep cool.

P501: Dispose of contents/container to to a regulated disposal site/contractor.

2.3. Other hazards

Other hazards: In use, may form flammable / explosive vapour-air mixture.

PBT: This product is not identified as a PBT/vPvB substance.

Section 3: Composition/information on ingredients

3.2. Mixtures

Hazardous ingredients:

ACETONE

EINECS	CAS	PBT / WEL	CLP Classification	Percent
200-662-2	67-64-1	-	Flam. Liq. 2: H225; Eye Irrit. 2: H319;	>50%
			STOT SE 3: H336; -: EUH066	

Section 4: First aid measures

4.1. Description of first aid measures

Skin contact: Remove all contaminated clothes and footwear immediately unless stuck to skin. Wash

immediately with plenty of soap and water.

Eye contact: Rinse immediately with plenty of water. Remove any contact lenses and open eyelids

wide apart. Continue to rinse for at least 15 minutes. Consult a doctor.

FILLTITE WOOD HARDENER RESIN

Page: 3

Ingestion: Do not induce vomiting. Provided the patient is conscious, wash out mouth with water

and give 200 - 300 ml (half a pint) of water to drink. Obtain immediate medical attention.

Inhalation: Remove casualty from exposure ensuring one's own safety whilst doing so. Consult a

doctor.

4.2. Most important symptoms and effects, both acute and delayed

Skin contact: There may be irritation and redness at the site of contact.

Eye contact: There may be irritation and redness. The eyes may water profusely.

Ingestion: There may be soreness and redness of the mouth and throat. May cause nausea,

headache, dizziness and intoxication. Gastrointestinal symptoms, including upset

stomach. Central nervous depression.

Inhalation: There may be irritation of the throat with a feeling of tightness in the chest. Symptoms

following overexposure may include the following: Headache, Fatigue, Dizziness,

Nausea, Vomiting.

Delayed / immediate effects: Immediate effects can be expected after short-term exposure.

4.3. Indication of any immediate medical attention and special treatment needed

Immediate / special treatment: Eye bathing equipment should be available on the premises. In case of accident or if

you feel unwell seek medical advice

Section 5: Fire-fighting measures

5.1. Extinguishing media

Extinguishing media: Suitable extinguishing media for the surrounding fire should be used. Alcohol resistant

foam. Carbon dioxide. Dry chemical powder. Water fog. DO NOT USE WATER JET.

5.2. Special hazards arising from the substance or mixture

Exposure hazards: Highly flammable. In combustion emits toxic fumes. Forms explosive air-vapour mixture.

Vapour may travel considerable distance to source of ignition and flash back.

5.3. Advice for fire-fighters

Advice for fire-fighters: Cool containers exposed to flames with water until well after the fire is out. Wear self-

contained breathing apparatus. Wear protective clothing to prevent contact with skin and

eyes.

Section 6: Accidental release measures

6.1. Personal precautions, protective equipment and emergency procedures

Personal precautions: Do not attempt to take action without suitable protective clothing - see section 8 of SDS.

Ensure adequate ventilation. If outside do not approach from downwind. If outside keep bystanders upwind and away from danger point. Mark out the contaminated area with signs and prevent access to unauthorised personnel. Turn leaking containers leak-side

up to prevent the escape of liquid. Eliminate all sources of ignition.

FILLTITE WOOD HARDENER RESIN

Page: 4

6.2. Environmental precautions

Environmental precautions: Contain the spillage using bunding. Do not allow to enter drains, sewers or

watercourses. Do not allow ANY environmental contamination. Spillages or uncontrolled discharges into watercourses must be IMMEDIATELY alerted to the Environmental Agency or other appropriate regulatory body.

6.3. Methods and material for containment and cleaning up

Clean-up procedures: Absorb into dry earth or sand. Transfer to a closable, labelled salvage container for

disposal by an appropriate method. Do not use equipment in clean-up procedure which

may produce sparks.

6.4. Reference to other sections

Reference to other sections: Wear protective clothing as described in Section 8 of this safety data sheet. See Section

11 for additional information on health hazards. Collect and dispose of spillages as

indicated in Section 13.

Section 7: Handling and storage

7.1. Precautions for safe handling

Handling requirements: Avoid direct contact with the substance. Static electricity and formation of sparks must be

prevented. Provide adequate ventilation. Do not handle in a confined space. Avoid the

formation or spread of mists in the air. Smoking is forbidden. Use non-sparking tools.

7.2. Conditions for safe storage, including any incompatibilities

Storage conditions: Store in a cool, well ventilated area. Keep container tightly closed. Keep only in original

container. Keep away from direct sunlight. Keep away from sources of ignition. Prevent the build up of electrostatic charge in the immediate area. Ensure lighting and electrical

equipment are not a source of ignition.

Suitable packaging: Must only be kept in original packaging.

7.3. Specific end use(s)

Specific end use(s): Wood Repair Solution

Section 8: Exposure controls/personal protection

8.1. Control parameters

Hazardous ingredients:

ACETONE

Workplace exposure limits: Respirable dust

.	~		~	
State	8 hour TWA	15 min SILI	│ 8 hour TWA	15 min. STEL
State	O HOULT WA	15 min. STEL	O HOUL I VVA	15 min. STEL

FILLTITE WOOD HARDENER RESIN

Page: 5

UK	1210 mg/m3	3620 mg/m3	-	-
----	------------	------------	---	---

DNEL/PNEC Values

Hazardous ingredients:

ACETONE

Туре	Exposure	Value	Population	Effect
DNEL	Dermal- Long Term	186 mg/kg/day	Workers	-
DNEL	Inhalation - Short Term	2420 mg/m ³	Workers	-
DNEL	Inhalation - Long Term	1210 mg/m³	Workers	-
DNEL	Oral - Long Term	62 mg/kg/day	Consumers	-
DNEL	Dermal - Long Term	62 mg/kg/day	Consumers	-
DNEL	Inhalation - Long Term	200 mg/m ³	Consumers	-
PNEC	Fresh water	10.6 mg/l	-	-
PNEC	Marine water	1.06 mg/l	-	-
PNEC	Water	21 mg/l	-	-
PNEC	Sediment	3.04 mg/kg	-	-
PNEC	Soil (agricultural)	33.3 mg/l	-	-
PNEC	STP	29.5 mg/l	-	-

8.2. Exposure controls

Engineering measures: Ensure there is sufficient ventilation of the area. Ensure lighting and electrical

equipment are not a source of ignition. Provide adequate ventilation to ensure that the

occupational exposure limit is not exceeded.

Respiratory protection: Self-contained breathing apparatus must be available in case of emergency.

Hand protection: The most suitable glove must be chosen in consultation with the gloves supplier, who

can inform about the breakthrough time of the glove material. The selected gloves should have a breakthrough time of at least 8 hours. Gloves should comply with European Standard EN374. It is recommended gloves are made of the following

material: Butyl gloves. Glove thickness 0.5mm.

Eye protection: Tightly fitting safety goggles. Ensure eye bath is to hand. Personal protective equipment

for eye and face protection should comply with European Standard EN166.

Skin protection: Protective clothing.

Environmental: DO NOT SMOKE IN WORK AREA! Avoid release to the environment.

Section 9: Physical and chemical properties

9.1. Information on basic physical and chemical properties

State: Liquid

Colour: Colourless
Odour: Characteristic odour

FILLTITE WOOD HARDENER RESIN

Page: 6

Evaporation rate: Fast

Oxidising: Not applicable.

Solubility in water: Soluble

Viscosity: Non-viscous

Boiling point/range°C: >35 Melting point/range°C: No data available.

Flammability limits %: lower: No data available. upper: No data available.

Flash point°C: -17c closed cup Part.coeff. n-octanol/water: No data available.

Autoflammability°C: No data available. **Vapour pressure:** No data available.

Relative density: 0.865 pH: 5-6

VOC g/l: 820

9.2. Other information

Other information: No data available.

Section 10: Stability and reactivity

10.1. Reactivity

Reactivity: Stable under recommended transport or storage conditions.

10.2. Chemical stability

Chemical stability: Stable under normal conditions. Stable at room temperature.

10.3. Possibility of hazardous reactions

Hazardous reactions: Hazardous reactions will not occur under normal transport or storage conditions.

Decomposition may occur on exposure to conditions or materials listed below.

10.4. Conditions to avoid

Conditions to avoid: Heat. Hot surfaces. Sources of ignition. Flames. Avoid Chlorinated hyrdrocarbons.

10.5. Incompatible materials

Materials to avoid: Strong oxidising agents. Strong acids. Amines. Strong reducing agents. Alkalis.

10.6. Hazardous decomposition products

Haz. decomp. products: In combustion emits toxic fumes of carbon dioxide / carbon monoxide.

Section 11: Toxicological information

11.1. Information on toxicological effects

Hazardous ingredients:

ACETONE

IVN	RAT	LD50	5500	mg/kg
ORL	MUS	LD50	3000	mg/kg

FILLTITE WOOD HARDENER RESIN

Page: 7

ORL	RAT	LD50	5800	mg/kg

Relevant hazards for product:

Hazard	Route	Basis
Serious eye damage/irritation	OPT	Hazardous: calculated
STOT-single exposure	-	Hazardous: calculated

Symptoms / routes of exposure

Skin contact: There may be irritation and redness at the site of contact.

Eye contact: There may be irritation and redness. The eyes may water profusely.

Ingestion: There may be soreness and redness of the mouth and throat. May cause nausea,

headache, dizziness and intoxication. Gastrointestinal symptoms, including upset

stomach. Central nervous depression.

Inhalation: There may be irritation of the throat with a feeling of tightness in the chest. Symptoms

following overexposure may include the following: Headache, Fatigue, Dizziness,

Nausea, Vomiting.

Delayed / immediate effects: Immediate effects can be expected after short-term exposure.

Section 12: Ecological information

12.1. Toxicity

Ecotoxicity values:

Species	Test	Value	Units
RAINBOW TROUT (Oncorhynchus mykiss)	96H LC50	5540	mg/l
PIMEPHALES PROMELAS	96H LC50	>100	mg/l
Daphnia magna	48H EC50	8800	mg/l
ACTIVATED SLUDGE	-	1000	mg/l
Daphnia magna	NOEC	2.212	mg/l

Hazardous ingredients:

ACETONE

BLUEGILL (Lepomis macrochirus)	LC50	8300	mg/l
--------------------------------	------	------	------

12.2. Persistence and degradability

Persistence and degradability: Biodegradable.

12.3. Bioaccumulative potential

Bioaccumulative potential: No bioaccumulation potential.

12.4. Mobility in soil

Mobility: Soluble in water.

FILLTITE WOOD HARDENER RESIN

Page: 8

12.5. Results of PBT and vPvB assessment

PBT identification: This product is not identified as a PBT/vPvB substance.

12.6. Other adverse effects

Other adverse effects: Negligible ecotoxicity.

Section 13: Disposal considerations

13.1. Waste treatment methods

Disposal operations: Transfer to a suitable container and arrange for collection by specialised disposal

company.

Disposal of packaging: Dispose of in a regulated landfill site or other method for hazardous or toxic wastes.

NB: The user's attention is drawn to the possible existence of regional or national

regulations regarding disposal.

Section 14: Transport information

14.1. UN number

UN number: UN1090

14.2. UN proper shipping name

Shipping name: ACETONE

14.3. Transport hazard class(es)

Transport class: 3

14.4. Packing group

Packing group: ||

14.5. Environmental hazards

Environmentally hazardous: No Marine pollutant: No

14.6. Special precautions for user

Special precautions: No special precautions.

Tunnel code: D/E
Transport category: 2

Section 15: Regulatory information

15.1. Safety, health and environmental regulations/legislation specific for the substance or mixture

Specific regulations: Not applicable.

15.2. Chemical Safety Assessment

Chemical safety assessment: A chemical safety assessment has not been carried out for the substance or the mixture

by the supplier.

FILLTITE WOOD HARDENER RESIN

Page: 9

Section 16: Other information

Other information

Other information: according to Regulation (EC) No. 1907/2006 (REACH) with its amendment Regulation

(EU) 2015/830

* indicates text in the SDS which has changed since the last revision.

Phrases used in s.2 and s.3: EUH066: Repeated exposure may cause skin dryness or cracking.

H225: Highly flammable liquid and vapour.

H319: Causes serious eye irritation.

H336: May cause drowsiness or dizziness.

Legal disclaimer: The above information is believed to be correct but does not purport to be all inclusive

and shall be used only as a guide. This company shall not be held liable for any

damage resulting from handling or from contact with the above product.